



Site:

Tested by:

Address:

Acme Cabling
John Doe

Written notes:

Cable ID: Building: Office: 1 Written notes:


Qualified: ✓ Coax (75 ohm)

Date	Time	Length	Version	S/N
2005.12.08.	12:49:31	321 m	V0.05.04	00000005

Cable ID: Building: Office: 2 Written notes:

Qualified: ✓ 10BASE-T; Wiremap Only; Telco
Disqualified: ✗ 1000BASE-T Reason: Crosstalk fault @ 18,9 m
 ✗ 100BASE-TX Reason: Crosstalk fault @ 18,5 m
 ✗ Voice Over IP Reason: Crosstalk fault @ 18,5 m


Date	Time	Length	Version	S/N
2005.12.08.	13:05:27	50,2 m	V0.05.04	00000005



Cable ID: Building: Office: 3 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N
2005.12.08.	13:22:42	34,6 m	V0.05.04	00000005



Cable ID: Building: Office: 4 Written notes:

Qualified: ✓ 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N
2005.12.08.	13:38:55	18,8 m	V0.05.04	00000005



Cable ID: Building: Office: 5 Written notes:

Qualified: ✓ Wiremap Only; Telco
Disqualified: ✗ 1000BASE-T Reason: Excessive Length
 ✗ 100BASE-TX Reason: Excessive Length
 ✗ 10BASE-T Reason: Excessive Length
 ✗ Voice Over IP Reason: Excessive Length

Date	Time	Length	Version	S/N
2005.12.08.	13:56:18	321 m	V0.05.04	00000005



Cable ID: Building: Office: 6 Written notes:

Qualified: ✓ 10BASE-T; Wiremap Only; Telco
Disqualified: ✗ 1000BASE-T Reason: Crosstalk fault
 ✗ 100BASE-TX Reason: Crosstalk fault
 ✗ Voice Over IP Reason: Crosstalk fault

Date	Time	Length	Version	S/N
2005.12.08.	15:11:29	11,0 m	V0.05.04	00000005





Site:

Tested by:

Address:

Acme Cabling
John Doe

Written notes:

Cable ID: Building: Office: 7 Written notes:

Disqualified: 1000BASE-T Reason: Wiremap
 100BASE-TX Reason: Wiremap
 10BASE-T Reason: Wiremap
 Voice Over IP Reason: Wiremap
 Wiremap Only Reason: Wiremap
 Telco Reason: Wiremap

Date	Time	Length	Version	S/N	Diagram
2005.12.08.	15:36:32	13,4 m	V0.05.04	00000005	

Cable ID: Building: Office: 8 Written notes:

Qualified: Telco
Disqualified: 1000BASE-T Reason: Wiremap (Split Pairs)
 100BASE-TX Reason: Wiremap (Split Pairs)
 10BASE-T Reason: Wiremap (Split Pairs)
 Voice Over IP Reason: Wiremap (Split Pairs)
 Wiremap Only Reason: Wiremap (Split Pairs)

Date	Time	Length	Version	S/N	Diagram
2005.12.08.	15:52:13	20,6 m	V0.05.04	00000005	

Cable ID: Building: Office: 9 Written notes:

Qualified: 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N	Diagram
2005.12.08.	16:02:58	30,9 m	V0.05.06	8734030	

Cable ID: Building: Office: 10 Written notes:

Qualified: 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N	Diagram
2005.12.08.	16:25:59	16,0 m	V0.05.06	8734030	

Cable ID: Building: Office: 11 Written notes:

Qualified: 1000BASE-T; 100BASE-TX; 10BASE-T; Voice Over IP; Wiremap Only; Telco

Date	Time	Length	Version	S/N	Diagram
2005.12.08.	16:42:19	37,7 m	V0.05.06	8734030	

Az Ön mérés technikai szakértője:

EQUICOM Mérés technikai Kft.
1162 Budapest, Mátyás király utca 12.
www.equicom.hu | info@equicom.hu